



# Full View

Aerial Imaging Solutions

## Overview

The areas in question consist of flat roofs with differing roof systems.

We have been instructed to comment on the overall condition of the roof system, identifying any noticed defects.

The weather condition at the time of the survey was approximately 18 Degrees C, clear.

Throughout this survey we will refer to blocks as below.





# Full View

Aerial Imaging Solutions



[thefullview.co.uk](http://thefullview.co.uk)



[aherman@thefullview.co.uk](mailto:aherman@thefullview.co.uk)



+44 (0)7969374276



# Full View

Aerial Imaging Solutions



[thefullview.co.uk](http://thefullview.co.uk)



[aherman@thefullview.co.uk](mailto:aherman@thefullview.co.uk)



+44 (0)7969374276



# Full View

Aerial Imaging Solutions



[thefullview.co.uk](http://thefullview.co.uk)



[aherman@thefullview.co.uk](mailto:aherman@thefullview.co.uk)



+44 (0)7969374276



# Full View

Aerial Imaging Solutions

## Analysis

### Roof A

A review of the flat roof system has highlighted several notable defects that may compromise its overall performance and longevity.

There is evidence of ponding water caused by areas of roof sagging, which suggests inadequate drainage and possible structural concerns. Additionally, the presence of differing roof types across the system raises concerns regarding the integrity of the junctions between these separate build-ups; in several locations, these junctions appear to have deteriorated visibly.

Furthermore, while some sections of the roof have undergone complete re-roofing, other areas exhibit significant signs of wear and deterioration, indicating inconsistent maintenance and potentially reduced waterproofing performance across the system.

### Roof B

A review of the flat roof system has highlighted several notable defects that may compromise its overall performance and longevity.

There is evidence of ponding water caused by areas of roof sagging, which suggests inadequate drainage and possible structural concerns. Additionally, the presence of differing roof types across the system raises concerns regarding the integrity of the junctions between these separate build-ups; in several locations, these junctions appear to have deteriorated visibly.

Furthermore, while some sections of the roof have undergone complete re-roofing, other areas exhibit significant signs of wear and deterioration, indicating inconsistent maintenance and potentially reduced waterproofing performance across the system.

### Roof C

Similar to the other roofs within scope, There is evidence of ponding water caused by areas of roof sagging, which suggests inadequate drainage and possible structural concerns.

Additionally, the presence of differing roof types across the system raises concerns regarding the integrity of the junctions between these separate build-ups; in several locations, these junctions appear to have deteriorated visibly.

Furthermore, while some sections of the roof have undergone complete re-roofing, other areas exhibit significant signs of wear and deterioration, indicating inconsistent maintenance and potentially reduced waterproofing performance across the system.

**Attached are extensive drone photographs of the roof, highlighting the noted defects. We have employed a colour coded severity system to help you identify the areas of most concern in the roof's current state.**





# FullView

Aerial Imaging Solutions

## **Roof D**

A review of the flat roof system has highlighted several notable defects that may compromise its overall performance and longevity.

There is evidence of ponding water caused by areas of roof sagging, which suggests inadequate drainage and possible structural concerns. Additionally, the presence of differing roof types across the system raises concerns regarding the integrity of the junctions between these separate build-ups; in several locations, these junctions appear to have deteriorated visibly.

Furthermore, while some sections of the roof have undergone complete re-roofing, other areas exhibit significant signs of wear and deterioration, indicating inconsistent maintenance and potentially reduced waterproofing performance across the system.

## **Roof E**

A review of the flat roof system has highlighted several notable defects that may compromise its overall performance and longevity.

There is evidence of ponding water caused by areas of roof sagging, which suggests inadequate drainage and possible structural concerns. Additionally, the presence of differing roof types across the system raises concerns regarding the integrity of the junctions between these separate build-ups; in several locations, these junctions appear to have deteriorated visibly.

Furthermore, while some sections of the roof have undergone complete re-roofing, other areas exhibit significant signs of wear and deterioration, indicating inconsistent maintenance and potentially reduced waterproofing performance across the system.

In addition to the above noticed defects, there are areas of fascia board that are failing further exposing the internal roof build up. These areas are visible from ground level.

## **Roof F**

A review of the flat roof system has highlighted several notable defects that may compromise its overall performance and longevity.

There is evidence of ponding water caused by areas of roof sagging, which suggests inadequate drainage and possible structural concerns. Additionally, the presence of differing roof types across the system raises concerns regarding the integrity of the junctions between these separate build-ups; in several locations, these junctions appear to have deteriorated visibly.

Furthermore, while some sections of the roof have undergone complete re-roofing, other areas exhibit significant signs of wear and deterioration, indicating inconsistent maintenance and potentially reduced waterproofing performance across the system.

**Attached are extensive drone photographs of the roof, highlighting the noted defects. We have employed a colour coded severity system to help you identify the areas of most concern in the roof's current state.**



#	Severity	Components	Issues	Comments	Page
1	3	Roof	Existing repair	Existing repair	<a href="#">4</a>
2	4	Roof	Damage	Deterioration to roof coverings	<a href="#">5</a>
3	4	Roof	Other Issue	Failed junction between the two roof coverings	<a href="#">6</a>
4	3	Roof	Existing repair	Existing repair	<a href="#">7</a>
5	4	Roof	Damage	Deterioration to flat roof system	<a href="#">8</a>
6	4	Roof	Other Issue	Failed junction between the two roof coverings	<a href="#">9</a>
7	3	Roof	Ponding water	Ponding water	<a href="#">10</a>
8	4	Roof	Other Issue	Failed junction between the two roof coverings	<a href="#">11</a>
9	4	Roof	Other Issue	Failed junction between the two roof coverings	<a href="#">12</a>
10	4	Roof	Damage	Damaged fascia	<a href="#">13</a>
11	4	Roof	Damage	Damaged fascia	<a href="#">14</a>
12	4	Roof	Damage	Damaged fascia	<a href="#">15</a>
13	3	Roof	Existing repair	Existing repair	<a href="#">16</a>
14	3	Roof	Ponding water	Ponding water	<a href="#">17</a>
15	3	Roof	Ponding water	Ponding water	<a href="#">18</a>
16	3	Roof	Ponding water	Ponding water	<a href="#">19</a>
17	3	Roof	Ponding water	Ponding water	<a href="#">20</a>
18	4	Roof	Damage	Deterioration to roof coverings	<a href="#">21</a>
19	4	Roof	Damage	Deterioration to roof coverings	<a href="#">22</a>
20	4	Roof	Damage	Deterioration to roof coverings	<a href="#">23</a>
21	4	Roof	Lap failure	Lap failure	<a href="#">24</a>
22	4	Roof	Damage	Deterioration to roof coverings	<a href="#">25</a>
23	4	Roof	Lap failure	Lap failure	<a href="#">26</a>



DJI\_20250324093956\_0010\_V.JPG

# 2

 Severity 4 Damage Roof**Alex Herman**

Deterioration to roof coverings



DJI\_20250324094230\_0032\_V.JPG

# 3

Severity 4

Other Issue

Roof

**Alex Herman**

Failed junction between the two roof coverings



DJI\_20250324094400\_0047\_V.JPG

# 4

Severity 3

⚠ Existing repair

📦 Roof



 **Alex Herman**  
Existing repair



DJI\_20250324101742\_0164\_V.JPG

# 13

Severity 3

⚠ Existing repair

📦 Roof

 **Alex Herman**  
Existing repair



DJI\_20250324101346\_0119\_V.JPG

# 16

Severity 3

⚠️ Ponding water

📦 Roof

**Alex Herman**  
Ponding water